





GTCA-ST straight PCB and GTCA-SF straight flex socket layouts

HIGH DENSITY





**NOTES:**

1. All patterns shown are for connector mounting side of PCB.
2. The Ø.172 (4.37) ref. holes shown are only required when the connector contains turning jackset hardware.
3. Reference GTCA-SF and GTCA-ST for connector details

Rectangular I/O and Printed Circuit Board Connectors

GTCA-ST straight PCB and GTCA-SF straight flex socket layouts


HIGH DENSITY

**NOTES:**

1. All patterns shown are for connector mounting side of PCB.
2. The Ø.172 (4.37) ref. holes shown are only required when the connector contains turning jacket hardware.
3. Reference GTCA-SF and GTCA-ST for connector details

GTCA-ST straight PCB and GTCA-SF straight flex socket layouts

HIGH DENSITY

**NOTES:**

1. All patterns shown are for connector mounting side of PCB.
2. The Ø.172 (4.37) ref. holes shown are only required when the connector contains turning jackset hardware.
3. Reference GTCA-SF and GTCA-ST for connector details